

September 2021

Volume IV

Environmental Assessment of the Proposed W12A Landfill Expansion, City of London



Table of Contents

Volume IV – Existing Conditions and Impact Assessment Reports

Appendices

APPENDIX D

Existing Conditions and Impact Assessment

- D.01 Air Quality Existing Conditions and Impact Assessment Report; completed by Golder Associates Ltd.
- D.02 Noise Existing Conditions and Impact Assessment Report; completed by Golder Associates Ltd.
- D.03 Groundwater Existing Conditions and Impact Assessment Report; completed by Dillon Consulting Limited and Golder Associates Ltd., respectively
- D.04 Surface Water Existing Conditions and Impact Assessment Report; completed by Dillon Consulting Limited and Golder Associates Ltd., respectively
- D.05 Biology (Aquatic and Terrestrial Ecosystems) Existing Conditions and Impact Assessment Report; completed by AECOM
- D.06 Land Use Existing Conditions and Impact Assessment Report; completed by MHBC
- D.07 Agricultural Resources Existing Conditions and Impact Assessment Report; completed by MHBC
- D.08 Archaeology Existing Conditions and Impact Assessment Report; completed by Golder Associates Ltd.
- D.09 Heritage Impact Assessment Report; completed by Golder Associates Ltd.
- D.10 Socio-economic Existing Conditions and Impact Assessment Report; completed by Golder Associates Ltd.
- D.11 Visual Existing Conditions and Impact Assessment Report; completed by Ron Koudys Landscape Architects Inc.
- D.12 Traffic Assessment in Support of the Environmental Assessment; completed by Dillon Consulting Limited
- D.13 Design and Operations Existing Conditions and Impact Assessment Report; completed by Golder Associates Ltd.

APPENDIX D

Existing Conditions and Impact Assessment

- D.01 Air Quality Existing Conditions and Impact Assessment Report; completed by Golder Associates Ltd.
- D.02 Noise Existing Conditions and Impact Assessment Report; completed by Golder Associates Ltd.
- D.03 Groundwater Existing Conditions and Impact Assessment Report; completed by Dillon Consulting Limited and Golder Associates Ltd., respectively
- D.04 Surface Water Existing Conditions and Impact Assessment Report; completed by Dillon Consulting Limited and Golder Associates Ltd., respectively
- D.05 Biology (Aquatic and Terrestrial Ecosystems) Existing Conditions and Impact Assessment Report; completed by AECOM
- D.06 Land Use Existing Conditions and Impact Assessment Report; completed by MHBC
- D.07 Agricultural Resources Existing Conditions and Impact Assessment Report; completed by MHBC
- D.08 Archaeology Existing Conditions and Impact Assessment Report; completed by Golder Associates Ltd.
- D.09 Heritage Impact Assessment Report; completed by Golder Associates Ltd.
- D.10 Socio-economic Existing Conditions and Impact Assessment Report; completed by Golder Associates Ltd.
- D.11 Visual Existing Conditions and Impact Assessment Report; completed by Ron Koudys Landscape Architects Inc.
- D.12 Traffic Assessment in Support of the Environmental Assessment; completed by Dillon Consulting Limited
- D.13 Design and Operations Existing Conditions and Impact Assessment Report; completed by Golder Associates Ltd.